



AHHA TESTING LABORATORY

A DIVISION OF
AUSTRALIAN HOME HEATING ASSOCIATION INC.

ABN 13 156 892 844

8/26 Stirling Street, Thebarton, South Australia 5031

Tel: (08) 8351 8056 Fax: (08) 8351 8059

Email: testlab@homeheat.com.au

A sponsor of



FLUE CLEANER PROJECT - TEST REPORT SUMMARY

CLIENT: Peter Leonard Hutchison
CLIENT REF: Order No. 218

REPORT NO: ATL61-03
DATE: 15 December 2003

TEST SPECIFICATION: AS/NZS 4013:1999

TEST FUEL: Hardwood

FLUE CLEANER DEVICE:-

Description: Hollow steel tube 150mm long, 30 to 60mm diameter with partially crimped ends containing the active ingredient (identified as a naturally occurring non-toxic solid material).

Manufactured by: Peter Leonard Hutchison

WORK REQUESTED:-

Measure particulate emissions, power output, efficiency and assess effect on soot/creosote deposition in the flue pipe. A typical medium sized fan-forced convection woodheater compliant with AS/NZS 4013:1999 was used for the test. Tests were conducted with and without the flue cleaner device fitted inside the firebox on high, medium and low air settings.

SUMMARY OF RESULTS:-

Emission performance

Reduction in particulate emissions of 50% on low setting, 24% on medium setting and 37% on high setting with the device fitted. Average reduction was 37%.

A reduction in particulate emissions indicates higher combustion efficiency.

Power output

6% increase in power output on the high setting with the flue cleaner installed. No significant change on the medium and low air settings.

Flue pipe condition

The interior surface of the flue pipe showed a complete conversion of the black/brown soot and creosote deposits into fine white ash on the high setting with the device fitted for 90% of its length. Cooler top 10 % of the flue pipe did not show any observable change. Burn time was 9 hours.



BEFORE

AFTER

A new thin layer of black soot was deposited in the pipe during the medium and low settings with the device fitted (these followed the high setting). Burn time was 41 hours.

The high, medium and low settings without the device fitted did not show any observable changes to the existing soot/creosote layer.

Flue Gas Temperature

A 17% increase in the flue gas temperature occurred on the high setting with the device fitted.

Investigation and Report by: Michael J Greenwood

Demi Brown
General Manager

Michael J Greenwood
Laboratory Manager

AHHA Testing Laboratory shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall AHHA Testing Laboratory be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Ref: c:\my documents\reports\at1 reports\repat161-03 summary sheet.doc Page 1 of 1